

From: [Terry Andrews](#)
To: [Moore, Gary](#)
Cc: [Omar Valdez](#); monica.harris@tceq.texas.gov
Subject: FW: Photos from CES
Date: Thursday, July 31, 2014 10:19:57 AM

Gary,

We just did a windshield survey of the site. Front gate was wide open but we didn't see anyone inside. Sections of the chain-link fence have been removed in several areas along the west fenceline of main facility area (east of Wayland street).

Photograph 001 is looking southeast at the back gate.

Photograph 002 is looking at the Bay Wash Out Building (where VB25141 and VB281842 are stored). Note that all the doors are wide open.

Photograph 003 is looking at the fence where the chain-link section has been removed.

Photograph 004 is of some staining along Wayland Street.

Photograph 005 is looking at another part of the fence where the chain-link section has been removed.

Photographs 006 and 007 show the open gate and water ponded in the parking lot.

Terry

From: Audrey Smith

Sent: Thursday, July 31, 2014 9:59 AM

To: Terry Andrews

Subject: Photos from CES

Here are the photos we took today at CES.

Audrey